


Blades Repair Catalogue

Main Rotor Blade
H125/H130/AS350/AS355

Tail Rotor Blade
H125/AS350/AS355

HELIBRAS
2026
English version

RAPAIR CATALOGUE - MAIN ROTOR BLADE PRELIMINARY INSPECTION / PRIOR BUDGET			
CUSTOMER NAME	CONTACT: (Phone / e-mail)		
BLADE REFERENCE (PN/SN)	TSN		
			
TABLE FOR AIRCRAFTS H130 / H125 / AS350 / AS355 (Value for just 1 blade)			
REPAIR RELATION:		PRICE USD - Man Power + Materials -	CYCLE (Working days)
A	Inspection + Replacement of Root end Polyurethane protection + Paint touch up	USD 2.149	10
	Inspection + Replacement of Root end Polyurethane protection + Static Balance + Total paint	USD 3.065	12
B	Inspection + Replacement of Polyurethane angle + Paint touch up (Total Painting see A+B)	USD 2.054	10
	Inspection + Replacement of Polyurethane lower surface + Paint touch up (Total Painting see A+C)	USD 3.236	13
D	Inspection + Repl. of Outboard Leading Edge#1 + Static Balance + Paint touch up (Total Painting see A+D)	USD 6.155	13
	Inspection + Repl. of Outboard Leading Edge#2 + Static Balance + Paint touch up (Total Painting see A+E)	USD 6.475	13
A+B	Inspection + Repl. Root end Pol. protection + Pol. Angle + Paint touch up	USD 2.721	12
	Inspection + Repl. Root end Pol. protection + Pol. Angle + Static Balance + Total paint	USD 3.639	15
A+C	Inspection + Repl. Root end Pol. protection + Pol. Lower Surface + Paint touch up	USD 3.903	14
	Inspection + Repl. Root end Pol. protection + Pol. Lower Surface + Static Balance + Total Paint	USD 4.819	16
A+D	Inspection + Repl. Root end Pol. protection + Outboard Leading Edge#1 + Static Balance + Paint touch up	USD 6.820	14
	Inspection + Repl. Root end Pol. protection + Outboard Leading Edge#1 + Static Balance + Total Paint	USD 7.525	16
A+E	Inspection + Repl. Root end Pol. protection + Outboard Leading Edge#2 + Static Balance + Paint touch up	USD 7.140	14
	Inspection + Repl. Root end Pol. protection + Outboard Leading Edge#2 + Static Balance + Total Paint	USD 7.845	16
B+C	Inspection + Replac. Polyurethane Angle + Polyurethane Lower Surface + Paint touch up (Total Painting see A+B+C)	USD 3.808	14
	Inspection + Replacement of both Outboard Leading Edge + Static Balance + Paint touch up (Painting total ver D+E+A)	USD 10.944	15
A+B+C	Inspection + Replacement of All Polyurethanes + Paint touch up	USD 4.475	15
	Inspection + Replacement of All Polyurethanes + Balance Static + Total Paint	USD 5.393	17
D+E+A	Inspection + Replac. of both Outboard leading edge + Pol. Root end protection + Static Balance+ Paint touch up	USD 11.611	16
	Inspection + Replac. of both Outboard leading edge + Pol. Root end protection + Static Balance+ Total Paint	USD 12.316	18
D+E+B	Inspection + Replac. of both Leading Edges + Polyuret. Angle + Static Balance + Paint touch up	USD 11.516	16
	Inspection + Replac. of both Leading Edges + Polyuret. Lower Surface + Static Balance + Paint touch up	USD 12.698	17
A+B+C+D+E	Inspection + Replac. of both Leading Edges + All Polyurethanes + Static Balance + Paint touch up	USD 13.937	19
	Inspection + Replac. of both Leading Edges + All Polyurethanes + Static Balance + Total Paint	USD 14.641	20
Indicate if you need of: Transportation <input type="checkbox"/> <input type="checkbox"/>		Yes <input type="checkbox"/> No <input type="checkbox"/>	Forecast of Sending to HB ____ / ____ / ____
<p>Notes and premises:</p> <ul style="list-style-type: none"> - Catalogue valid until January 2027. Consult present version on www.helibras.com.br on Services area. - The prices and cycles presented in this catalogue are used to reference only. A Commercial offer will be necessary to the service validation. A final offer shall be issued after the inspection at HB. - It is necessary to send this Solicitaion Card, filled, to Gabriela Silva - phone: +55 (35) 2143-4018, email: list.mro-componentes.hb@helibras.com.br, - In case it is necessary to change the METALIZATION PLAIT it will be charged a value of USD 138,00 and it will not be charged the man hour. - The Static balancing is always an obligation after the refinish painting and/or the replacement of Outboard Leading Edge #1 and/or #2. - Always, after the total painting service, it is necessary the replacement of Root end Polyurethane protection and Estatic Balancing. - The material used in Total Painting are included at the man hour value. - The price of man hour and pieces are to one blade only, make the multiplication for the desired blade amount. - The cycles are individuals, but consider the presented number to until 3 blades. Above this number get in touch. 			
		CONTACT: Phone: +55 (35) 2143-4018 - Gabriela Silva e-mail: list.mro-componentes.hb@helibras.com.br	

RAPAIR CATALOGUE - TAIL ROTOR BLADE PRELIMINARY INSPECTION / PRIOR BUDGET					
CUSTOMER NAME			CONTACT: (Phone / e-mail)		
BLADE REFERENCE (PN/SN)			TSN		
FOR AIRCRAFTS H125 / AS350 / AS355 (Values to Blades kit)					
REPAIR RELATION:				PRICE USD - Man Power + Materials -	CYCLE (Working days)
A	Inspection + Replac. of Poly. Root end + Touch up Painting			USD 2.926	10
	Inspection + Replac. of Poly. Root end+ Static Balance + Total Painting			USD 3.962	12
B	Inspection + Replac. of Poly. Lower Surface + Static Balance + Touch up Painting (To Total Painting see A+B)			USD 5.313	14
C	Inspection + Replac. of Outboard Leading Edge + Static Balance + Touch up Painting (Painting total ver A+C)			USD 10.129	15
A+B	Inspection + Replac. of Poly. Root end + Poly. Lower Surface + Static Balance + Touch up Painting			USD 6.034	15
	Inspection + Replac. of Poly. Root end + Poly. Lower Surface + Static Balance + Total Painting			USD 6.857	17
A+C	Inspection + Replac. Root end + Outboard Leading Edge + Static Balance + Touch up Painting			USD 10.852	16
	Inspection + Replac. Root end + Outboard Leading Edge + Static Balance + Total Painting			USD 11.674	18
B+C	Inspection + Replac. Poly. Lower Surface + Outboard Leading Edge + Static Balance + Touch up Painting			USD 13.025	18
A+B+C	Inspection + Replac. of all Polyurethanes + Outboard Leading Edge + Static Balance + Touch up Painting			USD 13.747	19
	Inspection + Replac. of all Polyurethanes + Outboard Leading edge + Static Balance Static + Total Painting			USD 14.569	20
Indicate if you need of: Transportation <input type="checkbox"/> <input checked="" type="checkbox"/> Box (Packing)				Forecast of Sending to HB Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> _____ / _____ / _____	
Notes and premises: <ul style="list-style-type: none"> - Catalogue valid until January 2027. Consult present version on www.helibras.com.br on Services area. - The prices and cycles presented in this catalogue are used to reference only. A Commercial offer will be necessary to the service validation. A final offer shall be issued after the inpection at HB. - Send this Solicitation Card, filled, to Gabriela Silva - phone: +55 (35) 2143-4018, email: list.mro-componentes.hb@helibras.com.br; - The Static balancing is always an obligation after the Total Painting and/or the replacement of Outboard Leading Edge #1 and/or #2 and/or Replacement of Polyurethane Lower Surface; - In case it is necessary to change the SEMI BEARING it will be charged an unit value of USD 1050,00 and it will not be charged the man hour. - Always, after the total painting service, it is necessary the replacement of Root end Polyurethane protection and Estatic Balancing. - The material used in Total Painting are included at the man hour value. - The price of man hour and pieces are configured to one blade kit. In case of necessity of one blade budget only, get in touch; - The cycles are individuals, but consider the presented to one tail rotor. Above this number get in touch 					
CONTACT: Phone: + 55 (35) 2143-4018 - Gabriela Silva e-mail: list.mro-componentes.hb@helibras.com.br					