Issue date: Oct 23, 2026

HELIBRAS

FLIGHT MANUAL REVISION STATUS
EC 725 AP
AIRCRAFT : EB

S/N (Operacio EB): 2853 – 2871 – 2888 – 2917 – 2933 – 2941 – 2953 – 2971 – 2976 – 3130
S/N (after aircraft retrofit from Basica EB to Operacio EB): 2764 – 2814 – 2830 – 2860 – 2869

This manual must contain the normal revision (RN) and rush revisions (RR) listed under the relevant issue (EDIT).

REGULATORY SECTION Volume 1			
SECTION / SUP	**EDIT. 1**	**DATE**	
0 → 5	RN 37	23-40	
.	.	.	
0 → 5 EB	RN 11	24-37	
.	.	.	
SUP.0	RN 20	23-02	
SUP.0 EB	RN 8	24-27	
SUP.1.1	RN 4	22-35	
.	.	.	
SUP.3.1	RN 4	22-35	
.	.	.	
SUP.5.1	RN 5	22-35	
SUP.5.1 EB	RN 4	23-14	
SUP.13	RN 7	22-10	
SUP. 13 EB	RN 4	23-14	
SUP.15.1	RN 6	24-15	
.	.	.	
SUP.16	RN 0	08-42	
.	.	.	
SUP.18	RN 1	24-15	R
.	.	.	
SUP.23	RN 2	06-17	
SUP.23 EB	RN 2	22-49	
SUP.24	RN 0	22-04	
.	.	.	
SUP.25.1	RN 4	22-35	
SUP.25.1 B-FAB	RN 3	23-14	
SUP.32	RN 0	08-42	
SUP.32 EB	RN 1	22-49	
SUP.33.1	RN 3	22-35	
.	.	.	

REGULATORY SECTION Volume 1		
SECTION / SUP	**EDIT. 1**	**DATE**
SUP.36	RN 0	08-42
SUP.42	RN 2	11-08
SUP.42 EB	RN 1	22-49
SUP.45	N/A	N/A
SUP.45 EB	RN 2	22-49
SUP.50	RN 1	08-42
.	.	.
SUP.54	RN 0	08-42
.	.	.
SUP.56	RN 1	17-20
SUP.56 EB	RN 2	22-49
SUP.56.1	N/A	N/A
SUP.56.1 EB	RN 2	22-49
SUP.59	RN 4	22-35
SUP.59 EB	RN 5	25-20
.	.	.
.	.	.

COMPLEMENTARY SECTION Volume 2		
SECT.	**EDIT. 1**	**DATE**
0, 6 → 10	RN 28	24-15
.	.	.
0, 6 → 10 EB	RN 13	24-44

Please refer to the Inventory Sheet of this Flight Manual for export control classification information.

N = New
R = Revised
D = Deleted