

| Report Number | STC Number        | Model        | Report Title                          | Part Number                                                        | Date      | Rev. |
|---------------|-------------------|--------------|---------------------------------------|--------------------------------------------------------------------|-----------|------|
| FMS-ECL-003   | SH94-31           | AS350 B,BA   | AIRFRAME-MOUNTED FUEL FILTER          | 350-600004                                                         | 28-May-15 | 5    |
| FMS-ECL-004   | SH94-31           | AS350 B1, B2 | AIRFRAME-MOUNTED FUEL FILTER          | 350-600004                                                         | 28-May-15 | 5    |
| FMS-ECL-007   | SH96-32           | AS350 BA, B2 | LEFT SIDE PILOT CONFIGURATION         | 350-400004                                                         | 01-Jun-23 | 9    |
| FMS-ECL-008   | SH96-39           | AS350        | TWO PLACE FORWARD PASSENGER SEAT (RH) | 350-200624                                                         | 05-Nov-12 | 6    |
| FMS-ECL-009   | SH97-15 / SH97-60 | AS350/355    | LH AND/OR RH CARGO PODS INSTALLATION  | 350-200814/824<br>350-201814/24<br>350-205414/24<br>355-200814/824 | 30-Jun-23 | 10   |
| FMS-ECL-010   | SH96-113          | AS350/355    | AFT CABIN DOORS REMOVED               |                                                                    | 15-Sep-16 | 2    |
| FMS-ECL-015   | SH02-42           | AS350 B3     | AIRFRAME-MOUNTED FUEL FILTER          | 350-600024                                                         | 17-Jun-15 | 8    |
| FMS-ECL-016A  | O-LSH98-344       | EC120 B      | NAVIGATION DISPLAY                    |                                                                    | 21-Dec-99 | 0    |
| FMS-ECL-019   | SH96-32           | AS350 B3     | LEFT SIDE PILOT CONFIGURATION         | 350-400074                                                         | 01-Jun-23 | 6    |
| FMS-ECL-022A  | O-LSH99-078       | EC120 B      | NAVIGATIONAL DISPLAY                  |                                                                    | 16-Apr-99 | 0    |
| FMS-ECL-027B  | O-LSH01-065       | AS350 B      | NAVIGATION DISPLAY                    |                                                                    | 15-Aug-01 | 0    |
| FMS-ECL-028A  | O-LSH00-017       | AS350 B3     | AUTOPILOT HEADING SUB MODE            |                                                                    | 04-Oct-00 | 0    |
| FMS-ECL-028B  | O-LSH01-056       | AS350 B      | AUTOPILOT HEADING SUB MODE            |                                                                    | 15-Aug-01 | 0    |

# AIRBUS

| Report Number | STC Number    | Model    | Report Title                                                             | Part Number | Date      | Rev. |
|---------------|---------------|----------|--------------------------------------------------------------------------|-------------|-----------|------|
| FMS-ECL-031A  | O-LSH99-143   | EC120 B  | NAVIGATION DISPLAY (S/N 1028)                                            |             | 15-Jun-99 | 0    |
| FMS-ECL-031B  | O-LSH99-302   | EC120 B  | NAVIGATION DISPLAY (S/N 1050)                                            |             | 16-Dec-99 | 0    |
| FMS-ECL-031C  | O-LSH01-028   | EC120 B  | NAVIGATION DISPLAY (S/M 1136)                                            |             | 15-Aug-01 | 0    |
| FMS-ECL-032A  | O-LSH01-087   | EC120 B  | FLIR 445G MARK 2 SYSTEM                                                  |             | 11-Dec-01 | 2    |
| FMS-ECL-035A  | O-LSH00-096   | AS350 B2 | FLOOR MOUNTED TORQUE METER                                               |             | 17-May-00 | 0    |
| FMS-ECL-037   | SH96-32       | AS350 B3 | LEFT SIDE PILOT CONFIGURATION                                            | 350-400164  | 01-Jun-23 | 6    |
| FMS-ECL-038A  |               | EC120 B  | DYNAMETRICS SYSTEMS CO. SLAVED<br>SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-038B  |               | EC120 B  | DYNAMETRICS SYSTEMS CO. SLAVED<br>SEARCHLIGHT SYSTEM                     |             | 27-Jun-01 | 0    |
| FMS-ECL-038C  |               | EC 120 B | DYNAMETRICS SYSTEMS CO. SLAVED<br>SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-038D  |               | EC 120 B | DYNAMETRICS SYSTEMS CO. SLAVED<br>SEARCHLIGHT SYSTEM (SLASS) MODEL S-301 |             | 10-Jul-03 | 0    |
| FMS-ECL-100A  | O-LSH02-6721D | EC120 B  | FLIR SYSTEM                                                              |             | 20-Nov-02 | 0    |
| FMS-ECL-101   |               | EC120 B  | SX-16 SEARCHLIGHT INSTALLATION                                           |             | 20-Nov-02 | 0    |
| FMS-ECL-102   | SH02-39       | EC120 B  | IMPROVED HEATING SYSTEM                                                  | 120-701014  | 19-Oct-10 | 4    |
| FMS-ECL-103   | SH02-42       | EC130 B4 | AIRFRAME-MOUNTED FUEL FILTER                                             | 130-600004  | 17-Jun-15 | 6    |
| FMS-ECL-105   | SH02-45       | EC130 B4 | LITTER KIT                                                               | 130-200034  | 28-Nov-07 | 1    |

Flight Manual Supplements

Last updated: Jan 13, 2026

| Report Number | STC Number   | Model            | Report Title                                                               | Part Number               | Date      | Rev. |
|---------------|--------------|------------------|----------------------------------------------------------------------------|---------------------------|-----------|------|
| FMS-ECL-106   | O-LSH03-70   | AS350 B3         | OPERATION WITH LEFT HAND PILOT DOOR REMOVED                                |                           | 01-Apr-03 | 0    |
| FMS-ECL-107   | SH94-29      | AS350/355        | LEFT HAND LITTER KIT                                                       | 350-200034,<br>350-200194 | 29-Aug-25 | 8    |
| FMS-ECL-108   | SH96-62      | AS350 BA, B2, B3 | RIGHT HAND LITTER KIT                                                      | 350-200144                | 10-Mar-17 | 5    |
| FMS-ECL-109   | SH03-15      | EC120 B          | SPECTROLAB SX-16 NIGHTSUN WITH MEEKER MOUNT (W/OUT PILOT'S CYCLIC CONTROL) | 120-901234                | 09-Nov-05 | 1    |
| FMS-ECL-110   | SH03-15      | EC120 B          | SPECTROLAB SX-16 NIGHTSUN WITH MEEKER MOUNT (WITH PILOT'S CYCLIC CONTROL)  | 120-901234                | 09-Nov-05 | 1    |
| FMS-ECL-111   | O-LSH03-207  | AS350 B3         | AUTOPILOT HEADING SUB-MODE                                                 | 350-401124                | 25-Mar-04 | 1    |
| FMS-ECL-112   | SH04-53      | EC130 B4         | OPERATION WITH SANDFILTER REMOVED                                          | 130-800034                | 30-Nov-04 | 0    |
| FMS-ECL-114   | SH03-15      | EC120 B          | SX-16 SEARCHLIGHT INSTALLATION WITH SLASS                                  | 120-901234                | 09-Nov-05 | 0    |
| FMS-ECL-115   | SH05-47      | EC 120 B         | FLIR U8500/U8500 SYSTEM INSTALLATION                                       | 120-901814                | 04-Dec-08 | 1    |
| FMS-ECL-116   | O-LSH05-310  | EC120 B          | VIDEO DOWNLINK SYSTEM                                                      | 120-902904                | 19-May-06 | 1    |
| FMS-ECL-117   | SH06-12      | AS350/355        | ENLARGED VERTICAL REFERENCE WINDOW                                         | 350/355-201154            | 28-Jan-15 | 4    |
| FMS-ECL-118   | O-LSH06-309  | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM ICDS-8                                     | 120-880204                | 18-Apr-07 | 3    |
| FMS-ECL-119   | O-LSH06-329  | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM ICDS-8                                     | 120-880204                | 16-Apr-07 | 2    |
| FMS-ECL-120   | O-LSH06-337  | EC120 B          | COMM NAV SYSTEM WITH DUAL SAGEM & AUTOPILOT                                | 120-880214                | 05-Apr-07 | 3    |
| FMS-ECL-121   | O-LSH07-050D | AS350 B3         | VIDEO DOWNLINK SYSTEM                                                      | 350-902924                | 20-Feb-06 | 0    |

| Report Number | STC Number    | Model    | Report Title                                | Part Number | Date      | Rev. |
|---------------|---------------|----------|---------------------------------------------|-------------|-----------|------|
| FMS-ECL-122   | O-LSH07-0491D | AS350 B3 | AUTOPILOT HEADING SUBMODE                   | 350-401144  | 28-Aug-08 | 1    |
| FMS-ECL-126   | O-LSH08-187D  | AS350    | VIDEO DOWNLINK SYSTEM                       | 350-902934  | 28-Aug-08 | 0    |
| FMS-ECL-127   | O-LSH08-282D  | EC120 B  | VIDEO DOWNLINK SYSTEM (STRATA DIGITAL)      | 120-902934  | 12-Dec-08 | 0    |
| FMS-ECL-128   | O-LSH08-288   | AS350 B3 | COMM NAV SYSTEM                             |             | 20-Jul-10 | 5    |
| FMS-ECL-129   | O-LSH08-288   | AS350 B3 | TWO PLACE FORWARD PASSENGER SEAT            | 350-200624  | 19-Dec-08 | 0    |
| FMS-ECL-130   | O-LSH08-288   | AS350 B3 | LH PILOT CONFIGURATION                      | 350-400164  | 19-Dec-08 | 0    |
| FMS-ECL-131   |               | EC120 B  | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880204  | 09-Jan-13 | 0    |
| FMS-ECL-132   |               | EC120 B  | COMM NAV WITH DUAL SAGEM ICDS-8 & AUTOPILOT | 120-880214  | 09-Jan-13 | 0    |
| FMS-ECL-133   | SH09-11       | AS350 B2 | DUAL SAGEM ICDS-6A INSTALLATION             | 350-873044  | 21-Apr-09 | 0    |
| FMS-ECL-134   | O-LSH09-245   | EC120 B  | DUAL SAGEM ICDS-6A                          | 120-872744  | 11-Aug-09 | 3    |
| FMS-ECL-135   | O-LSH09-200D  | AS350 B3 | VIDEO DOWNLINK SYSTEM                       | 350-902974  | 22-Jun-09 | 0    |
| FMS-ECL-136   | O-LSH09-210D  | AS350 B3 | VIDEO DOWNLINK SYSTEM                       | 350-902984  | 03-Jul-09 | 0    |
| FMS-ECL-137   | SH10-20       | EC130 B4 | OPERATION WITH DOORS REMOVED                |             | 18-Dec-13 | 2    |
| FMS-ECL-138   | O-LSH10-308   | EC120 B  | FLIR U8500 SYSTEM INSTALLATION              | 120-901864  | 30-Nov-10 | 1    |
| FMS-ECL-139   | O-LSH11-066   | EC135    | FLIR INSTALLATION                           | 135-901814  | 21-Apr-11 | 0    |

# AIRBUS

| Report Number | STC Number     | Model        | Report Title                      | Part Number | Date      | Rev. |
|---------------|----------------|--------------|-----------------------------------|-------------|-----------|------|
| FMS-ECL-140   | O-LSH11-065    | EC135        | SX-16 INSTALLATION                | 135-901214  | 21-Apr-11 | 0    |
| FMS-ECL-141   | O-LSH11-070    | EC135        | VIDEO DOWNLINK                    | 135-902714  | 15-Apr-11 | 0    |
| FMS-ECL-142   | O-LSH11-069    | EC135        | DOOR OPEN WARNING                 | 135-901014  | 15-Apr-11 | 0    |
| FMS-ECL-143   | O-LSH11-073/D  | AS350 B2     | COMM NAV SYSTEM                   | 350-880974  | 20-Apr-11 | 1    |
| FMS-ECL-144   | O-LSH11-068    | EC135        | CARGO COMPARTMENT MODS            | 135-200304  | 13-Apr-11 | 0    |
| FMS-ECL-145   | O-LSH11-0081/D | AS350 B3     | BMS DOWNLINK                      | 350-902994  | 10-May-11 | 1    |
| FMS-ECL-146   | O-LSH11-074/D  | EC135        | PULSE LIGHT INSTALLATION          | 135-902414  | 18-Apr-11 | 0    |
| FMS-ECL-148   | SH11-35        | EC130 B4     | ADJUSTABLE GLARE SHIELD           | 130-885114  | 20-Sep-11 | 0    |
| FMS-ECL-149   | O-LSH11-111    | AS350 B3     | ADJUSTABLE GLARE SHIELD           | ESK-1457    | 17-Jun-11 | 0    |
| FMS-ECL-151   | SH12-16        | AS350 B3     | OPERATION WITH SANDFILTER REMOVED | 350-800044  | 13-Mar-12 | 2    |
| FMS-AHCA-152  | SH14-10        | AS350 B2, B3 | LONGLINE ELECTRICAL PROVISIONS    | 350-900564  | 21-Feb-25 | 4    |
| FMS-ECL-153   | O-LSH12-189    | AS350 B3     | COMM NAV SYSTEM                   | 350-881014  | 10-Dec-12 | 0    |
| FMS-ECL-154   | SH02-42        | AS350 B3     | AIRFRAME-MOUNTED FUEL FILTER      | 350-600024  | 17-Jun-15 | 3    |
| FMS-ECL-155   | SH96-31        | AS350/355    | BATTERY RELOCATION                | 350-700324  | 27-Aug-24 | 2    |

Flight Manual Supplements

Last updated: Jan 13, 2026

| Report Number | STC Number              | Model        | Report Title                                             | Part Number   | Date      | Rev. |
|---------------|-------------------------|--------------|----------------------------------------------------------|---------------|-----------|------|
| FMS-AHCA-158  | SH20-44                 | EC130 T2     | AIRFRAME-MOUNTED FUEL FILTER                             | 130-600204    | 28-Oct-20 | 0    |
| FMS-AHCA-159  | O-LSH14-148/D<br>SH15-1 | AS355 NP     | LEAD ACID BATTERY INSTALLATION                           | 355-700024    | 12-Jun-15 | 2    |
| FMS-AHCA-160  | O-LSH14-150/D           | AS355 NP     | 50 AMP / LONGLINE / CAROUSEL                             | 355-900034    | 12-Dec-14 | 0    |
| FMS-AHCA-161  | O-LSH14-147/D           | AS355 NP     | FLIGHT FOLLOWING SATPHONE                                | 355-903014    | 12-Dec-14 | 0    |
| FMS-AHCA-162  | O-LSH14-149/D           | AS355 NP     | PULSE LIGHT INSTALLATION                                 | 355-902414    | 12-Dec-14 | 0    |
| FMS-AHCA-164  | O-LSH14-138/D           | AS355 NP     | COMM NAV SYSTEM                                          | 355-880054    | 12-Dec-14 | 0    |
| FMS-AHCA-165  | SH15-7                  | AS 355 N, NP | INSTALLATION OF HIGH VISIBILITY FORWARD<br>CABIN DOORS   | 350-202014    | 04-May-15 | 1    |
| FMS-AHCA-166  | SH12-52                 | AS355        | CABLE CUTTER INSTALLATION                                | 350-252004    | 19-Feb-15 | 0    |
| FMS-AHCA-168  | SH15-48                 | EC130 T2     | 50 AMP / LONGLINE / CAROUSEL SYSTEM                      | 130-900024    | 23-Oct-15 | 0    |
| FMS-AHCA-169  | O-LSH15-112/D           | EC130 T2     | GARMIN G500H DEVIATIONS TO FAA STC<br>SR09497RC-D        | 130-950304    | 06-Oct-15 | 0    |
| FMS-AHCA-170  | SH96-61                 | AS350/355    | CARGO MIRROR INSTALLATION                                | 350-200254/64 | 12-May-20 | 1    |
| FMS-AHCA-171  | SH00-1                  | AS350        | INSTALLATION OF HIGH VISIBILITY MAIN & AFT<br>CABIN DOOR | 350-202014    | 23-Mar-21 | 0    |
| FMS-AHCA-172  | SH21-25                 | AS 350 B3    | AIRFRAME MOUNTED FUEL FILTER WITH CRFS                   | 350-600044    | 06-Mar-23 | 1    |
| FMS-AHCA-173  | SH18-67                 | BK 117 D-2   | MICROWAVE DOWNLINK SYSTEM                                | 145-902714    | 28-Nov-18 | 0    |
| FMS-AHCA-174  | O-LSH18-170             | BK 117 D-2   | SEAT COVERS MODIFICATIONS                                | 145-701634    | 11-Dec-18 | 0    |

# AIRBUS

| Report Number | STC Number    | Model          | Report Title                                           | Part Number                  | Date      | Rev. |
|---------------|---------------|----------------|--------------------------------------------------------|------------------------------|-----------|------|
| FMS-AHCA-175  | O-LSH19-060/D | EC 130 T2      | HEAVY DUTY BATTERY INSTALLATION                        | 130-700244                   | 06-Jun-19 | 1    |
| FMS-AHCA-176  | O-LSH19-061/D | EC 130 T2      | GARMIN GTS-800 TRAFFIC ADVISORY SYSTEM<br>INSTALLATION | 130-870514                   | 01-May-19 | 0    |
| FMS-AHCA-177  | SH19-56       | EC 130 T2      | HEAVY DUTY BATTERY INSTALLATION                        | 130-700244                   | 16-Dec-19 | 0    |
| FMS-AHCA-178  | SH19-32       | BK117 D-2      | SUPPLEMENTAL CABIN HEATER INSTALLATION                 | 145-900004<br>145-910004     | 25-Oct-21 | 1    |
| FMS-AHCA-180  | SH20-47       | BK117 D-2      | ROTOR DISK LIGHTING INSTALLATION                       | 145-900634                   | 5-Jul-21  | 1    |
| FMS-AHCA-181  | SH20-47       | BK117 D-2      | CABIN HEAT OUTLETS CONTROL                             | 145-702104                   | 15-Dec-20 | 0    |
| FMS-AHCA-183  | SH21-22       | BK117 D-2, D-3 | TECHNISONIC TACTICAL RADIO INSTALLATION                | 145-900104<br>145-900114     | 14-Apr-21 | 0    |
| FMS-AHCA-184  | O-LSH22-154/D | AS 350 B3      | ANCILLARY AIRSPEED INDICATOR INSTALLATION              | 350-957314                   | 19-Dec-22 | 0    |
| C320I0190670  | SH24-19       | EC 120 B       | INSTALLATION OF SKID SHOES                             | C320I0190001                 | 28-Jun-24 | 0    |
| G430I0328670  | SH25-13       | EC 130 T2      | VHF-FM RADIO INSTALLATION                              | G430I0328001                 | 24-Jun-25 | 0    |
| H230I0355670  | SH25-21       | AS 350 B3      | AUDIO SYSTEM MODIFICATIONS                             | H230I0355001                 | 25-Nov-25 | 1    |
| H340I0183670  | O-LSH23-126D  | AS 350 B3      | INSTRUMENT PANEL MODIFICATIONS<br>INSTALLATION         | H340I0183101                 | 06-Nov-23 | 1    |
| H430I0307670  | SH24-30       | AS 350 B3      | SINGLE OR DUAL VHF-FM RADIO INSTALL                    | H430I0307001<br>H430I0307002 | 25-Nov-24 | 0    |
| L310I0332670  | O-LSH26-005   | EC 135 P3H     | EXTENDED INSTRUMENT PANEL                              | L310I0332001                 | 12-Jan-26 | 1    |
| L430I0335670  | O-LSH25-092   | EC 135 P3H     | TACTICAL RADIO INSTALLATION                            | L430I0335001                 | 16-Dec-25 | 0    |

Flight Manual Supplements

Last updated: Jan 13, 2026



| Report Number | STC Number | Model         | Report Title             | Part Number  | Date      | Rev. |
|---------------|------------|---------------|--------------------------|--------------|-----------|------|
| L520I0334670  | SH25-33    | EC135 P3H/T3H | DOOR OPEN CAUTION SYSTEM | L520I0334001 | 15-Dec-25 | 0    |